

Findings for walkthrough Centennial High School: January 24th, 2020

(WXXCHS20200002B4)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|---|----------------------------------|----------------|--------|
| FXXCHS2020001A59 | Blocked temperature sensors | Vending machines and microwave near thermostats can cast off heat | Staff dining | administration | Yes |
| FXXCHS2020001A5A | Artificial plants/trees | Live plant in admin offices need drip pan | Front office suite | administration | Yes |
| FXXCHS2020001A5B | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Diffusers dirty | Music practice room at main door | custodial | Yes |
| FXXCHS2020001A5C | General Cleanliness/Dust | | Student services hallway | custodial | Yes |
| FXXCHS2020001A5D | General Cleanliness/Dust | Dust on ledges | Student services hallway | custodial | Yes |
| FXXCHS2020001A5E | Blocked temperature sensors | Tv near thermostat | 703 | administration | Yes |
| FXXCHS2020001A5F | Tight seal on ceiling tiles | | 915 | custodial | Yes |
| FXXCHS2020001A60 | Tight seal on ceiling tiles | Stains near end of hall at stagecraft and exit doors near security camera and door to stage | 701_hall | custodial | Yes |
| FXXCHS2020001A61 | General Cleanliness/Dust | | 906 | custodial | Yes |
| FXXCHS2020001A62 | General Cleanliness/Dust | | 907 | custodial | Yes |
| FXXCHS2020001A63 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Returns, exhaust, supply diffusers very dirty | Stagecraft | custodial | Yes |
| FXXCHS2020001A64 | General Cleanliness/Dust | | 908 | custodial | Yes |
| FXXCHS2020001A65 | General Cleanliness/Dust | | 909 | custodial | Yes |
| FXXCHS2020001A66 | General Cleanliness/Dust | | 910 | custodial | Yes |
| FXXCHS2020001A67 | Miscellaneous finding | Remove clutter | Foods storage | administration | Yes |
| FXXCHS2020001A69 | General Cleanliness/Dust | | 911 | custodial | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|--|-------------------------------|----------------|--------|
| FXXCHS2020001A6A | Plumbing fixture leaking/draining slowly | Leaking sink | Foods pantry | building | No |
| FXXCHS2020001A6B | General Cleanliness/Dust | | 912 | custodial | Yes |
| FXXCHS2020001A6D | General Cleanliness/Dust | Food containers need to be wiped down | Foods pantry | custodial | Yes |
| FXXCHS2020001A6E | General Cleanliness/Dust | | 913 | custodial | Yes |
| FXXCHS2020001A6F | General Cleanliness/Dust | | 918 | custodial | Yes |
| FXXCHS2020001A70 | General Cleanliness/Dust | | Storage closet | custodial | Yes |
| FXXCHS2020001A71 | General Cleanliness/Dust | | Storage closet | custodial | Yes |
| FXXCHS2020001A72 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Return vent louvers are missing | 604 | administration | Yes |
| FXXCHS2020001A73 | General Cleanliness/Dust | | Storage closet | custodial | Yes |
| FXXCHS2020001A74 | Miscellaneous finding | Floor drain needs to be flushed | 604 | custodial | Yes |
| FXXCHS2020001A75 | Tight seal on ceiling tiles | Stained and missing tiles in loft | Drill team guard storage | custodial | Yes |
| FXXCHS2020001A77 | General Cleanliness/Dust | Need to remove clutter | Sendin office | administration | Yes |
| FXXCHS2020001A78 | General Cleanliness/Dust | | Storage closet | custodial | Yes |
| FXXCHS2020001A79 | Tight seal on ceiling tiles | Water stain in very narrow portion corner of the area | Concession stand | custodial | Yes |
| FXXCHS2020001A7A | General Cleanliness/Dust | | 914 | custodial | Yes |
| FXXCHS2020001A7B | Elevated moisture per moisture meter | Left end of stage high up pipe insulation to mechanical room heavily water stained | Stage | environmental | Yes |
| FXXCHS2020001A7C | Tight seal on ceiling tiles | Water stains near track lighting | 803 | custodial | Yes |
| FXXCHS2020001A7D | Miscellaneous finding | Corrosion on stall fixtures | Boys bathroom tech hall | | No |
| FXXCHS2020001A7E | Elevated moisture per moisture meter | Exterior end wall above metal shelving cmu has black staining possible mold. Looks like material was stored against wall and may have left staining. The metal roof deck above has signs of water damage. Clean wall and assess water entry. Correct and refinish wall | Storage room near boiler room | building | No |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|---|---|---|-------------|--------|
| FXXCHS2020001A7F | Floor coverings not level or secure (tile, carpets, wood board, etc.) | Carpet stained in multiple places | Media center | custodial | Yes |
| FXXCHS2020001A80 | Tight seal on ceiling tiles | | 307 | custodial | Yes |
| FXXCHS2020001A81 | General Cleanliness/Dust | | Dark room | custodial | Yes |
| FXXCHS2020001A82 | Tight seal on ceiling tiles | | Boiler room | custodial | Yes |
| FXXCHS2020001A83 | General Cleanliness/Dust | | Trainers office | custodial | Yes |
| FXXCHS2020001A84 | Floor coverings not level or secure (tile, carpets, wood board, etc.) | Carpet stained | 104 | custodial | Yes |
| FXXCHS2020001A85 | Artificial plants/trees | Drip pan for plant | 103 | | No |
| FXXCHS2020001A86 | Tight seal on ceiling tiles | Metal roof deck along back exterior wall. Sections along perimeter edge has staining. | Auxiliary gym | custodial | Yes |
| FXXCHS2020001A87 | Floor coverings not level or secure (tile, carpets, wood board, etc.) | Carpet stains | 202 | custodial | Yes |
| FXXCHS2020001A88 | Tight seal on ceiling tiles | Stained tiles | 201 | custodial | Yes |
| FXXCHS2020001A8A | Tight seal on ceiling tiles | Stain around drier vent pipe | Girls locker room ice machine laundry room | custodial | Yes |
| FXXCHS2020001A8B | Exterior doors not fully sealed (daylight) | | 903_hall | building | Yes |
| FXXCHS2020001A8C | Exterior doors not fully sealed (daylight) | | 912_hall | building | Yes |
| FXXCHS2020001A8E | Exterior doors not fully sealed (daylight) | | 408_hall | building | Yes |
| FXXCHS2020001A8F | Tight seal on ceiling tiles | Some type of staining around a sensor | Team room across from laundry room | custodial | Yes |
| FXXCHS2020001A91 | Exterior doors not fully sealed (daylight) | | 900 Hall | building | Yes |
| FXXCHS2020001A96 | Exterior doors not fully sealed (daylight) | | 506_hall | building | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|-----------------------------|---------------|----------|-------------|--------|
| FXXCHS2020001A98 | Tight seal on ceiling tiles | Painted tiles | 409 | custodial | Yes |