

# Findings for walkthrough Bonnie Branch Middle School: February 26th, 2020 (WXBBMS20200002E7)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXBBMS2020001CEE	Chemicals are capped	Items stored against elec panel and trash on floor	Electrical room 2	administration	Yes
FXBBMS2020001CF0	Excessive stuffed animals		3	administration	Yes
FXBBMS2020001CF1	Tight seal on ceiling tiles		45	custodial	Yes
FXBBMS2020001CF2	Chemicals are capped	Closet 18" of clearance at sprinkler head	8	administration	Yes
FXBBMS2020001CF3	Tight seal on ceiling tiles		44	custodial	Yes
FXBBMS2020001CF5	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)		42	administration	Yes
FXBBMS2020001CF6	Miscellaneous finding	Light lens coming down	Chem storage science 9	custodial	Yes
FXBBMS2020001CF8	Chemicals are capped	Housekeeping	Science office 9/10	administration	Yes
FXBBMS2020001CFA	Chemicals are capped	Housekeeping in closet	12	administration	Yes
FXBBMS2020001CFC	General Cleanliness/Dust		36	custodial	Yes
FXBBMS2020001CFD	Floor coverings not level or secure (tile, carpets, wood board, etc.)		hallway_36	building	No
FXBBMS2020001CFE	Uncomfortable temperature		33	building	No
FXBBMS2020001CFF	Tight seal on ceiling tiles		24	custodial	Yes
FXBBMS2020001D00	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)		30	administration	Yes
FXBBMS2020001D01	General Cleanliness/Dust		31	custodial	Yes
FXBBMS2020001D02	Tight seal on ceiling tiles		Computer	custodial	Yes
FXBBMS2020001D03	Tight seal on ceiling tiles		28	custodial	Yes
FXBBMS2020001D04	Tight seal on ceiling tiles	Ceiling tile askew	Kitchen	custodial	Yes
FXBBMS2020001D06	General Cleanliness/Dust		Portable 1	custodial	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXBBMS2020001D07	Tight seal on ceiling tiles		25	custodial	Yes
FXBBMS2020001D09	Tight seal on ceiling tiles		21	custodial	Yes
FXBBMS2020001D0A	Elevated moisture per moisture meter	Place work preserve for plumbing to assess water stained pipe insulation	Records Room Student zservices	building	No