

Findings for walkthrough Applications and Research Laboratory: March 11th, 2020

(WXXARL2020000305)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXARL2020001E68	Exterior doors not fully sealed (daylight)	Moisture in window by door exit	c39	building	No
FXXARL2020001E69	Tight seal on ceiling tiles		c35	custodial	Yes
FXXARL2020001E6A	Tight seal on ceiling tiles		C37a	custodial	Yes
FXXARL2020001E6B	Tight seal on ceiling tiles		c42-2	custodial	Yes
FXXARL2020001E6C	Tight seal on ceiling tiles		c42	custodial	Yes
FXXARL2020001E6D	Windows/Doors open	Panel under window coming off or loose check why and fix	c28_hall	building	No
FXXARL2020001E70	Exterior doors not fully sealed (daylight)		C29	building	No
FXXARL2020001E71	Tight seal on ceiling tiles		C29	custodial	Yes
FXXARL2020001E73	Exterior doors not fully sealed (daylight)		C30	building	No
FXXARL2020001E78	Tight seal on ceiling tiles		c50	custodial	Yes
FXXARL2020001E79	Tight seal on ceiling tiles	Blistering paint cement near window and paper shredder	c55	custodial	Yes
FXXARL2020001E7A	Tight seal on ceiling tiles		c55	custodial	Yes
FXXARL2020001E7B	Miscellaneous finding		Conference Room	building	No
FXXARL2020001E7C	Elevated moisture per moisture meter		B6	building	No
FXXARL2020001E7D	General Cleanliness/Dust		a8	custodial	Yes
FXXARL2020001E7E	Artificial plants/trees	Artificial in patient area	B8a	administration	Yes
FXXARL2020001E7F	Uncomfortable temperature	When A4B raises temp to 69 degrees, A2 becomes very hot and uncomfortable.	a1	building	No
FXXARL2020001E80	Uncomfortable temperature	When A4B raises temp to 69 degrees, A2 becomes very hot and uncomfortable.	a2	building	No
FXXARL2020001E81	General Cleanliness/Dust		north_greenhouse	custodial	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXARL2020001E82	Tight seal on ceiling tiles	Tile out of place vestibule near office and minor stain near second skylight	lobby	custodial	Yes
FXXARL2020001E83	Signs of insects or evidence of pest	Mice fecal matter throughout room, mostly on the floor.	a10b	building	No
FXXARL2020001E84	Tight seal on ceiling tiles	Stains	B40	custodial	Yes
FXXARL2020001E85	Exterior doors not fully sealed (daylight)		a10b	building	No
FXXARL2020001E86	Windows/Doors open		a10b	administration	Yes
FXXARL2020001E87	Tight seal on ceiling tiles	Stains near motion sensor	Hall outside of b63	custodial	Yes
FXXARL2020001E88	Tight seal on ceiling tiles		a10a	custodial	Yes
FXXARL2020001E89	Elevated moisture per moisture meter	Exit door frame showing signs of rust and bubbling	b63	building	No
FXXARL2020001E8A	Elevated moisture per moisture meter	Bubbling paint on exterior wall	B64	building	No
FXXARL2020001E8B	Windows/Doors open	Tried unsuccessfully to take a picture of crack and gauge in wall around window	a10a	building	No
FXXARL2020001E8C	Tight seal on ceiling tiles	Stains outside b62	b65_hall	custodial	Yes
FXXARL2020001E8D	Tight seal on ceiling tiles	Damaged and busted tile above fume hood	B62	custodial	Yes
FXXARL2020001E90	Tight seal on ceiling tiles	Stains in middle office and in large area outside of office b46a	b46	custodial	Yes
FXXARL2020001E91	Tight seal on ceiling tiles	B29 and b31 stained	b19	custodial	Yes
FXXARL2020001E92	Holes/Penetrations in Wall		a15	building	No
FXXARL2020001E94	Tight seal on ceiling tiles		a17	custodial	Yes
FXXARL2020001E96	Elevated moisture per moisture meter	Exit door outside of office a110 shows signs of blistering wall and door frame	b104	building	No
FXXARL2020001E97	Tight seal on ceiling tiles		a17	custodial	Yes
FXXARL2020001E98	Tight seal on ceiling tiles	Stained corner of room near pipe	A110	custodial	Yes
FXXARL2020001E99	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	Dirty diffusers	A110	custodial	Yes
FXXARL2020001E9A	Electrical equipment near sinks or source of water		a18	administration	Yes
FXXARL2020001E9B	Tight seal on ceiling tiles		a18	custodial	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXARL2020001E9C	Tight seal on ceiling tiles	Dirty tiles around diffusers	Room left of a107	custodial	Yes
FXXARL2020001E9D	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	Diffusers dirty	Room left of a107	custodial	Yes
FXXARL2020001E9E	Floor coverings not level or secure (tile, carpets, wood board, etc.)		a18	building	No
FXXARL2020001E9F	Tight seal on ceiling tiles	Cracked and out of place tiles	1b	custodial	Yes
FXXARL2020001EA0	Tight seal on ceiling tiles		a18	custodial	Yes
FXXARL2020001EA1	Floor coverings not level or secure (tile, carpets, wood board, etc.)	Spe area floor bulging in a section where floor trough was once located says gets worse after rains	b104	building	No
FXXARL2020001EA2	Elevated moisture per moisture meter	Staff indicates when rains roof drains leak down onto floor in spe area	b104	building	No
FXXARL2020001EA3	Tight seal on ceiling tiles	Huge hole in ceiling	Dark room	building	No
FXXARL2020001EA4	Exterior doors not fully sealed (daylight)	Along length of ceiling	Dark room	building	No
FXXARL2020001EA5	Windows/Doors open	Won't close and gaps	Dark room	building	No
FXXARL2020001EA6	Miscellaneous finding	Hole in wall	a21	building	No
FXXARL2020001EA7	Windows/Doors open	Exit door has trouble operating during extreme weather changes such has not closing. Daylight seen at bottom	a20	building	No
FXXARL2020001EA8	Plumbing fixture leaking/draining slowly	Water is said to show up on floor between computers 3 & 12 after short heavy rains	a22	building	No
FXXARL2020001EA9	Miscellaneous finding	Panel under 4th window from right is bulged out.	a20	building	No