

Findings for walkthrough Running Brook Elementary School: September 21st, 2018 (WXRBE2018000093)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXRBES2018000217	Visible mold on surfaces due to elevated relative humidity/dew point		kitchen and portables 111 and 115	custodial	Yes
FXRBES2018000218	Visible mold (leak)		kitchen and portables 111 and 115	environmental	Yes
FXRBES2018000219	Tight seal on ceiling tiles		kitchen and portables 111 and 115	administration	Yes
FXRBES201800021B	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		kitchen and portables 111 and 115	administration	Yes
FXRBES201800021C	Uncomfortable temperature		kitchen and portables 111 and 115	environmental	Yes