

Findings for walkthrough Running Brook Elementary School: November 21st, 2018

(WXRBS2018000099)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXRBES2018000222	Visible mold on surfaces due to elevated relative humidity/dew point		Band and Strings Room, Room 006	environmental	Yes