

Findings for walkthrough Running Brook Elementary School: August 27th, 2018 (WXRRES20180000A2)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXRBES201800022B	Visible mold on surfaces due to elevated relative humidity/dew point		Gymnasium Office	environmental	Yes