

# Findings for walkthrough Oakland Mills High School: August 9th, 2021

## (WXOMHS2021000365)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXOMHS2021001F26	Visible mold on surfaces due to elevated relative humidity/dew point		808 and 809	environmental	Yes