

Findings for walkthrough Oakland Mills High School: September 10th, 2021 (WXOMHS2021000371)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXOMHS2021001F33	Visible mold on surfaces due to elevated relative humidity/dew point		Room 809	environmental	Yes