Findings for walkthrough Oakland Mills High School: September 10th, 2021 (WXOMHS2021000371)

Tracking Number Finding Type Comments Location Assigned To Closed

FXOMHS2021001F33 Visible mold on surfaces due to elevated relative humidity/dew point

Room 809 environmental Yes