

# Findings for walkthrough Hollifield Station Elementary School: August 27th, 2021 (WXHSES202100037C)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXHSES2021001F3F	Visible mold on surfaces due to elevated relative humidity/dew point		Portable 71	environmental	Yes