

# Findings for walkthrough Lime Kiln Middle School: September 15th, 2021

## (WXLKMS2021000388)

| Tracking Number  | Finding Type   | Comments | Location  | Assigned To   | Closed |
|------------------|--|----------|---|---------------|--------|
| FXLKMS2021001F4C | Visible mold on surfaces due to elevated relative humidity/dew point |          | Closet on lower level under stairwell by main lower parking lot entrance door (near Rm. 20) | environmental | Yes    |