

# Findings for walkthrough Lime Kiln Middle School: September 15th, 2021 (WXLKMS2021000388)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXLKMS2021001F4C	Visible mold on surfaces due to elevated relative humidity/dew point		Closet on lower level under stairwell by main lower parking lot entrance door (near Rm. 20)	environmental	Yes