

Findings for walkthrough Clarksville Elementary School: September 27th, 2022 (WXXCES20220003E6)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXCES2022001FBE	Penetrations not sealed	Salts and/or blemishes on exterior wall.	gymnasium	building	Yes
FXXCES2022001FBF	Blocked temperature sensors	Pictures attached to flat thermostat sensors on wall on the left side of classroom doorway.	art room 101	administration	Yes
FXXCES2022001FC0	Penetrations not sealed	Hole in brick exterior near existing ventilation condensate drain.	art room 101	building	Yes
FXXCES2022001FC1	General Cleanliness/Dust	Visible dust accumulation on various horizontal surfaces, such as file cabinets.	room 302	custodial	Yes
FXXCES2022001FC2	Wall-mounted unit requires cleaning/general preventative maintenance	Grime and mildew on components of wall mounted air conditioning unit.	gym office	building	Yes
FXXCES2022001FC3	Wall-mounted unit requires cleaning/general preventative maintenance	Grime and mildew on components of wall mounted air conditioning unit.	room 318	building	Yes
FXXCES2022001FC4	Holes/Penetrations in Wall	Exterior brick wall has two penetrations (top and bottom) near electrical conduit and down spout.	courtyard across from gym	building	Yes
FXXCES2022001FC5	Penetrations not sealed	Exterior brick wall (west side), there is a hole between alarm box and upper left corner of the window.	exterior of staff lounge	building	Yes
FXXCES2022001FC6	General Cleanliness/Dust	Visible dust accumulation on various horizontal surfaces, such as file cabinets.	room 508	custodial	Yes
FXXCES2022001FC7	Non-issued disinfectants/aerosol sprays	Aerosol disinfectant spray observed on bookshelf.	room 508	administration	Yes