

Findings for walkthrough Applications and Research Laboratory: November 3rd, 2022 (WXXARL202200040D)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXARL202200206C	Visible mold on surfaces due to elevated relative humidity/dew point		A16 A/B	environmental	Yes
FXXARL202200206E	Visible mold on surfaces due to elevated relative humidity/dew point		A16 A/B	building	Yes