

Findings for walkthrough Applications and Research Laboratory: November 3rd, 2022 (WXXARL202200040D)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|----------|----------|---------------|--------|
| FXXARL202200206C | Visible mold on surfaces due to elevated relative humidity/dew point | | A16 A/B | environmental | Yes |
| FXXARL202200206E | Visible mold on surfaces due to elevated relative humidity/dew point | | A16 A/B | building | Yes |