

Timestamp	Observation:	Room Number or Location/Name:	Comments for this room:	ADMINISTRATION	CUSTODIAL	FACILITIES WORK ORDER NUMBER	IEQ WORK ORDER NUMBER	ASSIGNED DATE	COMPLETION DATE	30-DAY REVISIT	CLOSED
3/2/2018 11:20:10	04: VENTS: Dirty, obstructed (Wall, Ceiling)	N110			X						
3/2/2018 11:23:00	04: VENTS: Dirty, obstructed (Wall, Ceiling)	N118			X						
3/2/2018 12:52:38	04: VENTS: Dirty, obstructed (Wall, Ceiling)	Bathrooms across from N119			X						
3/2/2018 12:55:41	04: VENTS: Dirty, obstructed (Wall, Ceiling)	B100			X						
3/2/2018 13:00:29	04: VENTS: Dirty, obstructed (Wall, Ceiling)	Kitchen - B115 and dishwashing			X						
3/8/2018 15:03:14	04: VENTS: Dirty, obstructed (Wall, Ceiling)	A219			X						
3/8/2018 15:04:05	04: VENTS: Dirty, obstructed (Wall, Ceiling)	F-124			X						
3/8/2018 15:07:30	04: VENTS: Dirty, obstructed (Wall, Ceiling)	N200	Vents obstructed		X						
3/8/2018 15:18:27	04: VENTS: Dirty, obstructed (Wall, Ceiling)	A207 closet	Accumulated dust on closet ceiling around sprinkler head		X						
3/2/2018 13:03:48	06: CLEANLINESS: Dust, trash	B121	Clutter		X						
3/2/2018 13:08:25	06: CLEANLINESS: Dust, trash	A107	Items hanging from ceiling, clutter, flags		X						
3/2/2018 11:34:14	08: CEILING TILES: Stained, broken, holes, painted	B105	Near closet		X						
3/2/2018 11:50:04	08: CEILING TILES: Stained, broken, holes, painted	B114			X						
3/2/2018 11:59:01	08: CEILING TILES: Stained, broken, holes, painted	B120			X						
3/2/2018 12:02:39	08: CEILING TILES: Stained, broken, holes, painted	Outside of f105	Hole		X						
3/2/2018 12:11:59	08: CEILING TILES: Stained, broken, holes, painted	F103	Tile falling down and escutian plate			64680		3/26			
3/2/2018 13:13:28	08: CEILING TILES: Stained, broken, holes, painted	A109	Stained tile		X						
3/2/2018 13:28:38	08: CEILING TILES: Stained, broken, holes, painted	Student services workroom			X						
3/8/2018 14:44:28	08: CEILING TILES: Stained, broken, holes, painted	A204 office			X						
3/8/2018 14:47:27	08: CEILING TILES: Stained, broken, holes, painted	Stairwell across from 200			X						
3/8/2018 14:52:18	08: CEILING TILES: Stained, broken, holes, painted	B202	Missing ceiling tile grid		X						
3/8/2018 15:03:37	08: CEILING TILES: Stained, broken, holes, painted	A219			X						
3/8/2018 15:05:52	08: CEILING TILES: Stained, broken, holes, painted	2nd Floor N Stairwell	Ceiling tile out of place		X						
3/8/2018 15:20:27	08: CEILING TILES: Stained, broken, holes, painted	A209 storage			X						
3/8/2018 15:22:06	08: CEILING TILES: Stained, broken, holes, painted	Electrical closet across from a213	Missing tile		X						
3/2/2018 11:34:49	09: WATER DAMAGE: Spotting, mildew, paint irregularities (ceilings, walls, doors, windows)	B105	Hvac closet pipe insulation. Replace insulation			63111		3/16			

